

DETAILS OF CONTRACTS AWARDED ON SINGLE TENDERS ON NOMINATION BASIS									
PERIOD : JANUARY'2024									
Sl. No.	Name of the Project	Details of Work	Name of the Awardee	Type or Nature of Nomination	Reason / Justification for awarding the work on Nomination Basis	Work Order No. and Date	Value of Contract Awarded	Related DFP under which the Work has been awarded	Status of Work
1	DSTPS	Procurement of Ready Cut Gasket for Boiler and Coal Mill section at DSTPS DVC.	M/S REX SEALING & PACKING INDUSTRIES PVT. LTD.	Single(Urgency)	Procurement of Spares are required during overhauling of Burner System. Presently Unit # 2, DSTPS, is under shutdown for Overhauling and installation of DeNOx Package. The minimum quantity required during this overhauling is 80 Nos. for Item Code 150201021033 and 40 Nos. for Item Code: 150201021032. Earlier, these spares were issued to MTPS Unit # 8, during its overhauling on Loan basis (Ref STI # DVC/MTPS/27122022/REQ/00019 Dated: 13/01/2023. As on date they have not returned these spares and have stated that these spares will be returned after the placement of PO and subsequent supply of the same. The tender floated from DSTPS was cancelled as quoted price of L1 bidder was too higher (66% high) than the departmental estimate based on LPP. Tender floated again with revised DE based on Budgetary offer and it is under process. These spares are also not available in KTPS and BTPS (BUS enclosed). Hence, we have no other option but to procure these spares on ground of Urgency.	NO : DVC/Contract/DSTPS/Boiler & Coal Mill Maint./C&M Purchase & Contract/Supply/00229 Dated 24/01/2024	123200	9.3	

	2	DSTPS	Phase Array Ultrasonic Testing (PAUT) for Boiler Tube Welding Joints and Oxide Scale Measurement of Boiler tubes during overhauling of Unit#2 at DSTPS, DVC, Andal	VIBRANT NDT SERVICES	Single(Urgency)	<p>The job required during overhauling of the Pressure part of the boiler. Presently Unit # 2, DSTPS, is under shutdown for Overhauling and installation of DeNOX Package. The job is required for testing of the Boiler Tubes (Oxide Scale measurement: for measurement of scale deposition inside the tubes) and the welded joints (PAUT: defect inspection in the welds joints) in the tubes and based on this inspection the condition of the tubes and joints are assessed and future course of action is planned. If the tube or welding joint does not pass this test, it needs to be replaced. It is very much necessary for the healthiness of the boiler during running of the units and the test can be done only during the overhauling period since the tubes are within reach during overhauling period as temporary scaffoldings are erected. A work order was issued on M/s Web Mechanical Engineers through tendering process vide WO No. DVC/Contract/Head Quarter/Boiler & Coal Mill Maint./CMM/Works and Service/00010 and GeM W.O No.:GEMC-511687719048077 Dated 05/12/2023, but the vendor has neither submitted the SDBG/Agreement nor mobilised manpower and tools despite several requests from our side (correspondence mails are attached for reference). The vendor seems very reluctant to execute the job as he is not giving any concrete date to start the job and a concrete execution plan. It is seriously hampering the overhauling work as on date as the manpower for pressure parts has already started their work and the absence of the PAUT and Oxide Scale measurement has stalled the testing processes. Hence, we have no other option but to award the contract on ground of Urgency.</p>	DVC/Contract/DSTPS/Boiler & Coal Mill Maint./C&M Purchase & Contract/Works and Service/00066	547472.5	4.5(i)	
--	---	-------	--	----------------------	-----------------	---	--	----------	--------	--